### **Aeroprakt Ltd**

Address: 24, Polyova str., 03056 Kyiv, Ukraine

E-mail: aeroprakt.kiev@gmail.com

phone: +38 044 496 77 21, web: https://aeroprakt.kiev.ua/

# AEROPRAKT NOTIFICATION

No. N A22LS-25

## HOLES IN THE FLAPERON HINGE AXLES IN A22LS AND A22L2 AIRCRAFT

#### **Repeating symbols:**

Please, pay attention to the following symbols throughout this document marking important information.

- ▲ WARNING: Identifies an instruction, which if not followed may cause serious injury or even death.
- CAUTION: Denotes an instruction, which if not followed, may cause severe damage.
- ◆ **NOTE:** Information useful for better handling.

Release date: 27.10.2022

**Effective date: 27.10.2022** 

Completion date:

Superseded notice: none

Model: A22LS and A22L2

Serial number(s) affected: All A22LS and A22L2 aircraft

AEROPRAKT NOTIFICATION No. N A22LS-25

#### 1) Planning information

#### 1.1) Aircraft affected

All A22LS and A22L2 aircraft.

#### 1.2) Reason

Inquiries from the aircraft operators.

#### 1.3) Subject

Holes in the flaperon hinge axles in A22LS and A22L2 aircraft.

#### 1.4) Compliance

Compliance with this notification is obligatory for ensuring compliance to type certificate.

#### 1.5) Approval

The technical content of this Service Bulletin has been approved by Aeroprakt.

#### 1.6) Manpower

None.

#### 1.7) Mass data

Mass change – none.

#### 1.8) Revision of other documents

None.

#### 1.9) Spare parts

None.

#### 2) Spare parts information

None.

Address: 24, Polyova str., 03056 Kyiv, Ukraine

E-mail: aeroprakt.kiev@gmail.com

phone: +38 044 496 77 21, web: https://aeroprakt.kiev.ua/

AEROPRAKT NOTIFICATION No. N A22LS-25

#### 3) Accomplishment / Instructions

■ Do not put any safety pins or wire in the holes in the flaperon hinge axles (see the photo below). It is a type-certified design. Failure to follow this instruction will invalidate compliance of your aircraft to the type design and type certificate.

◆ These holes are not intended for any safety pins or wire in the flaperon hinge axles. They are present because the flaperon hinge axles are made of a standard part (a pin with a hole for the safety pin/wire) the hole in which may be necessary for locking or safety pin/wire in other aircraft components. These holes in the flaperon hinge axles do not affect in any way or degree the normal function of the hinges.



Address: 24, Polyova str., 03056 Kyiv, Ukraine

E-mail: aeroprakt.kiev@gmail.com

phone: +38 044 496 77 21, web: https://aeroprakt.kiev.ua/