# **Aeroprakt Ltd**

Address: 24, Polyova str., 03056 Kyiv, Ukraine

E-mail: air@prakt.kiev.ua, aeroprakt.kiev@gmail.com

phone: +38 044 496 77 21, fax: +38 044 496 77 31

# AEROPRAKT SERVICE BULLETIN

No. SB A32-06

# INSPECTION OF WINDSCREEN GLASS OF A32 AND A32L AIRCRAFT

### **Repeating symbols:**

Please, pay attention to the following symbols throughout this document marking important information.

- ▲ WARNING: Identifies an instruction, which if not followed may cause serious injury or even death.
- CAUTION: Denotes an instruction, which if not followed, may cause severe damage.
- ◆ **NOTE:** Information useful for better handling.

Release date: 02.12.2019

**Effective date: 03.12.2019** 

Completion date:

Superseded notice: none

Model: A32 and A32L

Serial number(s) affected: All A32 aircraft to and including serial No. 116

and all A32L aircraft to and including serial No. 025

#### **AEROPRAKT**

# **SERVICE BULLETIN**

No. SB A32-06

#### 1) Planning information

#### 1.1) Aircraft affected

All A32 aircraft to and including serial No. 116 and all A32L aircraft to and including serial No. 025.

#### 1.2) Reason

Experience of operation.

#### 1.3) Subject

Windscreen glass.

#### 1.4) Compliance

Compliance with this Service Bulletin is mandatory for all affected aircraft for flight safety reasons!

#### 1.5) Approval

The technical content of this Service Bulletin has been approved by Aeroprakt.

#### 1.6) Manpower

Estimated work: 20-40 minutes.

#### 1.7) Mass data

Mass change – insignificant.

#### 1.8) Revision of other documents

None.

#### 1.9) Spare parts

None.

#### 2) Spare parts information

None.

Address: 24, Polyova str., 03056 Kyiv, Ukraine

E-mail: <u>air@prakt.kiev.ua</u>, <u>aeroprakt.kiev@gmail.com</u> phone: +38 044 496 77 21, fax: +38 044 496 77 31

# AEROPRAKT SERVICE BULLETIN No. SB A32-06

- 3) Accomplishment / Instructions
- 3.1) Subsection **3.2** of **"3 Structures"** section of AEROPRAKT A32 Airplane Maintenance Manual shall be written as follows:

"Inspect the glass from outside and inside for cracks. In case if any cracks are found that protrude beyond the glass attachment strips, the glass must be replaced. Contact your local dealer for glass replacement instructions."

- ▲ WARNING: The glazing material is not resistant to fuels, oils and solvents. Spilling those liquids on glazing may cause its dimness and cracking.
- 3.2) Subsection **3.2** of "**3 Structures**" section of AEROPRAKT A32L Airplane Maintenance Manual shall be written as follows:

"Inspect the glass from outside and inside for cracks. In case if any cracks are found that protrude beyond the glass attachment strips, the glass must be replaced. Contact your local dealer for glass replacement instructions."

▲ WARNING: The glazing material is not resistant to fuels, oils and solvents. Spilling those liquids on glazing may cause its dimness and cracking.

Address: 24, Polyova str., 03056 Kyiv, Ukraine

E-mail: <u>air@prakt.kiev.ua</u>, <u>aeroprakt.kiev@gmail.com</u> phone: +38 044 496 77 21, fax: +38 044 496 77 31