

AEROPRAKT INFORMATION BULLETIN

REVISIONS IN THE IB A-22-06 IB A-22-11

MANDATORY

1. Planning information

1.1) Aircraft affected

All versions of Aeroprakt-22 aircraft with metal spring of the nose landing gear.

1.2) Reason

Experience of operation of A22 aircraft.

1.3) Subject

Paragraph 1.4) of IB A-22-06.

1.4) Approval

The technical content of this Information Bulletin has been approved by Aeroprakt.

1.5) Revision of other documents

None

2. Accomplishment / Instructions

2.1) Replace the contents of paragraph 1.4) with the following:

Replacement of the nose landing gear leg spring shall be performed after 5000 landings or upon detecting cracks.